## MONTHLY INSPECTION AT IMAGE (CBWTF), MALAMPUZHA

Date: 09-11-2022, Wednesday

Inspected by: Sruthi Chandran AE-1

## Inspection Details:-

Sl No.	DETAILS	STATUS / REMARKS
1.	BMW Collection	51.847 MT ( Average collection daily of October)
2.	Incinerators	1 - Shut down for maintenance; 2,3,4,5 – Working
3.	No. of Incinerators	5
4.	Online Continuous Emission Monitoring System (OCEMS)	OCEMS No.1 – New Rotary (Dry Scrubber) – Plant No.1  OCEMS No.2 – Old Parishudh – Plant No.1  OCEMS No.3 – Old Rotary – Plant No.2  OCEMS No.4 – Thermax – Plant No.2  OCEMS No.5 – New Alpha – Plant No.3
5.	Barcode Scanning	Equipment Dismantled, Not in Use. The shed had caught fire. It is not fully rebuilt; scanning not done. Weighing using weigh bridge is functional; hence weight of BMW handled is obtained.
6.	Unit Premises	Neat & Tidy

7.       8.	All Plastic Items, Synthetic Rubber Items, Metals, Glass Bottles, Other miscellaneous items ETP	Sent to Aryaja Industri Working, Ultra Filtration	, , , , , , , , , , , , , , , , , , ,	
0.	LII	(Last effluent sample was conforming to limits even without UF)		
9.	Online Continuous Effluent Monitoring System (OCEMS)	Working; Partial connectivity shown in OCEMS as Two incinerators are not uploading values (maintenance)		
10.	Rain Water Harvesting Pond	Three-Fourth full (no over flow seen)		
11.	Backlog	NIL		
12.	Sample collected for Analysis	Collected from:-  (i) Filter feed Tank  (ii) ETP Outlet		
13.	Sample Analysis	Collected on 12.10.2022		
	Results	Filter feed tank	ETP outlet	
		pH – 8.42	pH- 8.11	
		TSS – BDL	TSS-BDL	
		BOD – 12.6	BOD-5.3	
		COD – 112 mg/L	COD-104 mg/l	
		Oil & Grease – BDL	Oil & Grease- BDL	
14.	Hazardous Waste	Stored in Roofed Area – Almost full		



**INCOMING BMW COLLECTION AREA** 



**INCINERATOR 1** 



**SCRAP PROCESSING SHED** 



**SCRAP PROCESSING AREA** 



PROPOSED SITE FOR BARCODE SCANNING



GLASS BOTTLLE PROCESSING UNIT