MONTHLY INSPECTION AT IMAGE (CBWTF), MALAMPUZHA

Date: 14-09-2022, Wednesday

Inspected by: Sruthi Chandran AE-1, Arya Sidharth - GEA

Inspection Details:-

Sl	DETAILS	STATUS / REMARKS
No.		
1.	BMW Collection on	39 MT
	the day before	
	inspection.	
2.	Incinerators	1,2,3,4,5 –Working
3.	No.of Incinerators	5
	working	
4.	Online Continuous	OCEMS No.1 – New Rotary (Dry
	Emission Monitoring	Scrubber) – Plant No.1
	System (OCEMS)- status of working	OCEMS No.2 – Old Parishudh – Plant No.1
	status of Working	OCEMS No.3 – Old Rotary – Plant No.2
		OCEMS No.4 – Thermax – Plant No.2
		OCEMS No.5 – New Alpha – Plant No.3
5.	Barcode Scanning &	Equipment Dismantled; Not in use. The
	weighing	shed had caught fire. It is not fully rebuilt;
		scanning not done. Weighing using weigh
		bridge is functional, hence weight of BMW
		handled is obtained.
6.	Unit Premises	Neat & Tidy

7.	Processing of Plastic ,Synthetic Rubber	Segregation, shredding seen satisfactory	g,bailing,storage -
	Items, Metal, Glass Bottles, Other miscellaneous items	Processed recyclable - S Industries, NIDA, Kan	• •
8.	ETP	Working, Ultra Filtration not working; but effluent quality of last month's sample was achieving standards.	
9.	Online Continuous Effluent Monitoring System (OCEMS)	Working	
10.	Rain Water Harvesting Pond	Three-Fourth full	
11.	Backlog	NIL	
12.	Sample collected for Analysis	Collected from:- (i) Filter feed Tank (ii) ETP Outlet (iii) Rain Water Harves	sting Pond
13.)22
	Results	Filter feed tank	ETP outlet
		pH – 8.25	pH- 8.49
		TSS – BDL	TSS-BDL
		BOD – 2.8	BOD-2.2
		COD – 68 mg/L	COD-68 mg/l
		Oil & Grease – BDL	Oil & Grease- BDL

		All the parameters are within limit in ETP outlet.
14.	Hazardous Waste Incinerator Ash &	Stored in Roofed Area –
	ETP Sludge	Regularly collected by KEIL.



BMW WASTE COLLECTION AREA



AUTOCLAVE AREA



SEGREGATION OF WASTE



OCEMS 1



OCEMS 2



SCRAP PROCESSING AREA



ETP OUTLET



PROPOSED SITE FOR BARCODE SCANNING



RAIN WATER HARVESTING POND